

安徽明汉新材料股份有限公司

批准人：环保部

日期：2024年4月16日

安徽凯泽新材料有限公司

容安环境事件完全

[illegible]

Figure 1: A schematic diagram of a 1D lattice chain. The chain consists of sites labeled 1, 2, 3, ..., N. Site 1 is occupied by a spin-1/2 particle (represented by a circle with a dot). Site 2 is occupied by a spin-1/2 particle (represented by a circle with a dot). Site 3 is occupied by a spin-1/2 particle (represented by a circle with a dot). Site N is occupied by a spin-1/2 particle (represented by a circle with a dot). The sites are connected by horizontal lines representing nearest-neighbor interactions. The diagram is labeled "Figure 1" and "1D Lattice Chain".

[illegible]

1. The first step in the process is to identify the problem or issue that needs to be addressed. This involves gathering information and understanding the context of the problem.

1. 对位法与对位法原理的讲解。

3、观摩人员及评估人员准备好摄像器材，进行拍摄图片及摄像，做

记录。

3、观摩人员及评估人员准备好摄像器材，进行拍摄图片及摄像，做

应急物资；

占打力，而

进行回收，并

人员进入现场；

(4) 物资保障组提供防毒面具、铁锹、吨桶、吨袋等


(5) 抢险救援组立即切断管道内物料流动，关闭阀门

水阀门是否关闭

(6) 抢险救援组身着防护措施对现场流失的各废

废水送往污水站处理；

(1) II级响应处置流程图



II级响应处置流程图

演练总结

预案名称：污泥泄露事故应急演练

演练地点：RTO 北侧道路

组织部门：安环部

总指挥：李松

演练时间：2024 年 04 月 20 日


预案适宜性充分性评审	适宜性： ☒ 全部能够执行 ☐ 执行过程不够顺利 ☐ 明显不适宜		
	充分性： ☒ 完全满足应急要求 ☐ 基本满足需要完善 ☐ 不充分，必须修改		
	人员	☒ 迅速到位 ☐ 未及时到位	


		演练情况	物资到位情况	现场物资： ☒ 现场物资充分 ☐ 现场准备不充分 ☐ 现场物资严重缺乏		
			个人防护：	☒ 全部人员防护到位 ☐ 个别人员防护不到位 ☐ 部分人员防护不到位		
		协调	参演单位：演练中，参演单位能够按照预案要求，迅速到位，处置得当。			
		实际效果评价	☒ 达到预期目标 ☐ 基本达到目的，部分环节有待改进 ☐ 没有达到目标，需重新演练			
		外部支援部门和协作	报告上级：	☒ 报告及时 ☐ 联系不上		
			消防部门：	☒ 按要求协作 ☐ 行动迟缓		
			医疗救援部门：	☒ 按要求协作 ☐ 行动迟缓		
		总结	有效性			
			存在问题	无		
			改进措施	无		



网络重传时间: 2024年4月20日 下午4:05:21

36°36'39.652"N	121°32'39.897"E
浙江省宁波市北仑区	





网络真实时间: 2017年1月20日下午4:22:44

穿戴好防护用品，进行现场应急处置。